

Latest revision of this document:

2014-05-23

Listed below are official software versions.

Version: 5720R15
Release date: 2014-05-09

- Added
 - Smart Price Adaption, Menu 4.1.6.
 - +Adjust added
- Alarms
 - Sensor alarm for BT14, hot gas, added. Alarm number 14.
 - Info alarm for BT61, heat medium flow, added. Alarm number 61.
 - When alarm "low exhaust air temperature" (64) the RMU40 (if installed) will light up and show the alarm icon and alarm number.
- Menus
 - Calculated flow temperature is now calculated on filtered outdoor temperature.
 - Added a page in the start guide that requests to set the ventilation.
 - Exhaust air fan (and possible supply fan) is not operating when the start guide is active.
 - Setting for the exhaust and supply air fans removed from the start guide.
 - "QR service code" added in start guide and service info 3.1.
 - Cannot set the prio times between 1-9 minutes.
 - Function "BlockFreq" added which allows you to set two frequency spans on 5Hz where the compressor is not allowed to operate. Menu 5.1.24.
 - Accessory SOLAR42 added.
 - Improved setup for stop addition in menu 4.9.2 from -20C to -25C.
 - General update and improvement of language translations.
- AUX, menu 5.4, Soft in-/output.
 - Add option "activate fan speed 1(NC)". Activate speed 1-4 (NO) remains as previously.
 - Add option "external alarm (NC)". Activates info alarm 995 "alarm from external input/signal".
 - Add option "External alarm (NO)". Activates info alarm 995 "alarm from external input/signal".
- General bug fixes and improvements.