



2009-11-26 Ute 6,0°C Kurva 4,5 2,5 Retur till 30°C från 35°C FL ca 45°C  
Cirkulationspump läge 2 .

Element nr 2 gillestuga




Label	Value
Sp1	39.2 °C
Sp2	32.5 °C
Dt1: [ana.Sp1.temp] - [ana.Sp2.temp]	6.6 °C

### Element 3 Lilla toan nere




Label	Value
Sp1	36.5 °C
Sp2	35.5 °C
Dt1: [ana.Sp1.temp] - [ana.Sp2.temp]	1.0 °C

## Element 4 Hall källare




Label	Value
Sp1	35.6 °C
Sp2	32.8 °C
Dt1: [ana.Sp1.temp] - [ana.Sp2.temp]	2.7 °C

## Element 5 Tvättstugan




Label	Value
Sp1	33.5 °C
Sp2	29.9 °C
Dt1: [ana.Sp1.temp] - [ana.Sp2.temp]	3.6 °C

By pass 6 Duschen  
Nere




Label	Value
Sp1	34.8 °C
Sp2	34.5 °C
Dt1: [ana.Sp1.temp] - [ana.Sp2.temp]	0.3 °C

Element 8 Hobbyrummet




Label	Value
Sp1	31.0 °C
Sp2	28.0 °C
Dt1: [ana.Sp1.temp] - [ana.Sp2.temp]	3.0 °C

Element 8 Hobbyrummet – med dom 2 första elementen nedskruvade



Label	Value
Sp1	37.1 °C
Sp2	32.6 °C
Dt1: [ana.Sp1.temp] - [ana.Sp2.temp]	4.5 °C


## Ytterdörr – värmeläckage cid dörrspringa



Label	Value
Sp1	19.4 °C
Sp2	13.6 °C
Sp3	15.5 °C
Sp4	17.4 °C
Dt1: [ana.Sp1.temp] - [ana.Sp2.temp]	5.9 °C
Dt2: [ana.Sp3.temp] - [ana.Sp4.temp]	-1.9 °C



Ventilation nere



Label	Value
Sp1	8.3 °C
Sp2	11.5 °C
Sp3	12.9 °C
Sp4	16.5 °C